



A TETRA TECH COMPANY

East Tamaki Laboratory

Coffey Services (NZ) Limited

144A Cryers Road, East Tamaki NZ 2013
PO Box 58877, Botany, Manukau NZ 2163

Phone: +64 9 272 3375
Fax: +64 9 272 3378

Material Test Report

Report No: ETAM17S-12237-1

Issue No: 1

Client: Landscaping Direct Ltd
PO Box 1629
Taupo 3351


Principal: Shaun Fredricksen

Project No.: 773-ETAM00534AA

Project Name: Scoria Properties Testing - Takanini


Lot No.: TRN:

Tests indicated as not accredited are outside the scope of the laboratory's accreditation.
(This document may not be altered or reproduced except in full. This report relates only to the positions tested.)



Approved Signatory: Ramir Casidsid
(Laboratory Team Leader)
IANZ Accredited Laboratory Number:105
Date of Issue: 7/12/2017

Sample Details		Other Test Results			
Sample ID:	ETAM17S-12237	Description	Method	Result	Limits
Client Sample:	SAP 7	Moisture Content (%)	NZS 4407:2015 Test 3.1	8.7	
Date Sampled:		Sand Equivalent	NZS 4407:2015 Test 3.6	96	
Source:	Unknown (Sampled by Client)	Shaking Method		Manual	
Material:	SAP 7 AP10 Scoria Aggregates	Date Tested		1/12/2017	
Specification:	No Specification	Solid Density (t/m ³)	NZS 4407:2015 Test 3.7.1	2.43	
Sampling Method:	Unknown (Not IANZ Endorsed)	History		Oven Dried	
Project Location:	35 Rangi Road, Takanini	Date Tested		6/12/2017	
Sample Location:	Not specified				



Comments

Work Order No : ETAM17W04235